

S19T (3): EX-S19T-3

Good Condition, Reconditioned-Out of Box

Condition Report:

Scratches on both sides on the Battery Box and a small dent in the RHS Floor shroud.

