

S19 QUEST (5): EX-SCT670630-5

Average Condition, Reconditioned-Out of Box

Condition Report:

Scuffs and scratches on both rear fenders, LHS Floor shroud, RHS of Battery Box cover and a scuff on the RHS tiller shroud.

