

S19 QUEST (6): EX-SCT670630-6

Average Condition, Reconditioned-Out of Box

Condition Report:

Scuff and scratches on both sides of the Floor shroud, both side of the front Floor shroud, both sides of the Battery Box cover and one scuff at the rear.

